



Vergleichstabelle Danfoss – Suntec – OEG

für linksdrehende Ölbrennerpumpen

Danfoss		Suntec	Bemerkungen	OEG Art.-Nr.	
BFP 11 L3	071N0141		in Einstrangsystem	OEG Service-Pumpe AUV 47 L	112 000 000
BFP 20 L3	071N0108	AN 47 C 1342 6P	Danfoss: Welle 2 Flächen Suntec: Welle 1 Fläche	OEG Service-Pumpe AUV 47 L + Umrüstsatz	112 000 000 112 102 003
BFP 20 L3	071N0125				
BFP 20 L3	071N0127				
BFP 20 L3	071N0161				
BFP 20 L3	071N0168				
BFP 20 L3	071N0212				
BFP 20 L5	071N0114				
BFP 21 L3	071N0102	AS 47 C 1538 6P 0700 L AL 35 C 9528 6P 0700 L	Austausch Suntec MV Spule erforderlich Suntec Art.Nr. 3713824110V	OEG Service-Pumpe AUV 47 L	112 000 000
BFP 21 L3	071N0104				
BFP 21 L3	071N0111				
BFP 21 L3	071N0113				
BFP 21 L3	071N0119				
BFP 21 L3	071N0122				
BFP 21 L3	071N0123				
BFP 21 L3	071N0130				
BFP 21 L3	071N0132				
BFP 21 L3	071N0147				
BFP 21 L3	071N0148				
BFP 21 L3	071N0150				
BFP 21 L3	071N0151				
BFP 21 L3	071N0156				
BFP 21 L3	071N0164				
BFP 21 L3	071N0170				
BFP 21 L3	071N0175				
BFP 21 L3	071N0176				
BFP 21 L3	071N0179				
BFP 21 L3	071N0182				
BFP 21 L3	071N0185				
BFP 21 L3	071N0189				
BFP 21 L3	071N0193				
BFP 21 L3	071N0197				
BFP 21 L3	071N0217				
BFP 21 L3	071N0214				
BFP 21 L3 LE	071N2118	AL 35 D 9529 6P 0700 L	Suntec Pumpe benötigt MV Bausatz ALE OEG Art.Nr. 112101200	OEG Service-Pumpe AUV 47 L	112 000 000
BFP 21 L5	071N0107	AS 47 C 1538 6P 0700 L AL 35 C 9528 6P 0700 L		OEG Service-Pumpe AUV 47 L	112 000 000
BFP 21 L5	071N0116				
BFP 21 L5	071N0158				
BFP 21 L5	071N0172				
BFP 21 L5	071N0194				
BFP 21 L5	071N0202				
BFP 31 L3	071N0115	AS 47 C 1538 6P 0700 L AL 35 C 9528 6P 0700 L	in Einstrangsystem	OEG Service-Pumpe AUV 47 L	112 000 000
BFP 31 L3	071N0133				
BFP 31 L3	071N0149				
BFP 31 L3	071N0190				
BFP 31 L3	071N0191				
BFP 31 L3	071N0192				
BFP 41 L3	071N0160		Danfoss MV Spule seitlich	OEG Service-Pumpe AUV 47 L	112 000 000
BFP 41 L3	071N0174				
BFP 41 L3	071N1213				



Vergleichstabelle Danfoss – Suntec – OEG

für rechtsdrehende Ölbrennerpumpen



Danfoss		Suntec	Bemerkungen	OEG Art.-Nr.	
BFP 11 R3	071N0155		in Einstrangsystem	OEG Service-Pumpe AUV 47 R	112 000 010
BFP 20 R3	071N0118	AN 47 A 1326 6P		OEG Service-Pumpe AUV 47 R + Umrüstsatz	112 000 010 112 102 003
BFP 20 R3	071N0128				
BFP 20 R3	071N0162				
BFP 20 R3	071N0169				
BFP 20 R5	071N0129				
BFP 20 R5	071N0180				
BFP 21 R3	071N0109	AS 47 A 1536 6P 0700 R AL 35 A 9526 6P 0700 R	in Einstrangsystem	OEG Service-Pumpe AUV 47 R	112 000 010
BFP 21 R3	071N0112				
BFP 21 R3	071N0136				
BFP 21 R3	071N0154				
BFP 21 R3	071N0157				
BFP 21 R3	071N0167				
BFP 21 R3	071N0171				
BFP 21 R3	071N0198				
BFP 21 R3	071N0208				
BFP 21 R3	071N0214				
BFP 21 R3	071N0215				
BFP 21 R3	071N1215				
BFP 21 R5	071N0120	AS 47 A 1536 6P 0700 R AL 35 A 9526 6P 0700 R		OEG Service-Pumpe AUV 47 R	112 000 010
BFP 21 R5	071N0159				
BFP 21 R5	071N0173				
BFP 21 R5	071N0195				
BFP 21 R5	071N0207				
BFP 41 R3	071N0137		Danfoss MV Spule seitlich	OEG Service-Pumpe AUV 47 R	112 000 010
BFP 41 R3	071N0138				
BFP 41 R3	071N0196				

