

Druck- / Temperatur-Diagramm zu WESA - Kugelhahn Nr.9350 bis 9397

Zoll / °C	-20°C	-10°C	0°C	+20°C	+40°C	+60°C	+80°C	+100°C	+120°C	+140°C	+150°C	+160°C	+170°C	+180°C
1/4" - 1"	40	40	40	40	40	37	34	30	26	22	17	12	6	0
1 1/4" - 2"	25	25	25	25	25	22	19	16	13	10	7	4	2	0

